CERTIFICATE OF ANALYSIS

Milbank Manufacturing Company

1400 E. Havens P.O. Box 754

Kokomo, IN 46903-0754 Attn: Ronda S. Yeakley

Purchase Order: 206941

Invoice Number:

Order #: 97-12-379 Date: 12/19/97 07:36

Work ID: Effluent Water Composite

Date Received: 12/12/97
Date Completed: 12/18/97

Client Code: MILBANK MFG

SAMPLE IDENTIFICATION

Sample
Number I

Sample

Description

01

Effluent Water Composite

Sample Number Sample

Description

This report may not be reproduced except in full, without the written approval of the laboratory. All results relate only

to the items tested.

This report contains a total number of pages: 02

Certified By

TEST RESULTS BY SAMPLE

Sample: 01AW Effluent Water Composite Collected: 12/11/97 Category: WATER

| Test Description | Result | Limit | Units | Analyzed | Bv |
|------------------|--------|-------|-------|----------|-----|
| Iron, ICAPES | 0.358 | 0.010 | | 12/18/97 | |
| Lead, ICAPES | <0.040 | 0.040 | mg/L | 12/18/97 | JAR |
| Silver, ICAPES | <0.010 | 0.010 | mg/L | 12/18/97 | JAR |
| Zinc, ICAPES | 2.580 | 0.010 | mg/L | 12/18/97 | JAR |



PHONE (317) 290-1471 FAX (317) 290-1670

ESG **boratories**

5933 71st Street * Indianapolis, IN 46278

Phone (317) 290-1471 * Fax (317) 290-1670

C.AIN OF CUSTODY RECORD

| Client Name: ESG Work Order #: 912379 | | | | | r#: | T | Filter | Preservation Codes: A = Acid | | | | | | | | | | |
|--|----------|--------|-----------|---|------------------------------------|-----|-----------------|------------------------------------|----------|----------|----------|----------|----------|----------|-------------|------|----------|-------------------------|
| Project No: Project Name: Sampler(s) Signature; | | | | | | | Total Number | | Analyses | | | | | | | | | |
| ļ | Un | | -14 | le | | | of | / | 77 | × / | | | / | / / | / / | / / | / / | B = Base C = Cool 4° |
| Stat.No | | | COMP | GRAI | STATION LOCA | | Containers | <u></u> | XXX | \angle | \angle | \angle | \angle | \angle | | | Comments | |
| | 12-11-9 | 70-300 | × | | Ef fluen | Pit | 1 | X | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | |
| | · | | | } | | | | | | | | | | | | | | |
| - | | | | <u> </u> | | | | | | | | | | | | | | |
| - | | | | | | | | | | | | | | | | | | |
| - | | | | | | | | | | | | | | | | | | |
| | | | * | | | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | | | | | • | |
| | | | | | | | | | | | | | | | | | | |
| | | | | | | | | • | | | | - | | | | | | |
| | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | - | | | |
| | | | | | | | | | | | | | - | | - 5 | | | |
| | | | | | | | | - | | | | - | | | | | | |
| | | | | | | | | | | | | | - | | | | | |
| | | | | | | | | | | | - | | \dashv | | | | | |
| Relinqui | shed By: | | Date / | Time | Received By: | Da | te / Time | Addit | ional I | nform | ation: | | | | | | | |
| Relinquished By: Received By: Received By: | | | Bind)12 | 1/128:40 | e / Time Additional Information: | | | | | | | | | | | | | |
| Relinquished By: Date / Time Received By: Da | | | te / Time | Are samples suspected to be: Flammable Corrosive Toxic | | | | | | | | | | | | | | |
| | | | | | | | Were | sampl | es rece | ived i | ntact | and n | roner | lv pres | served? Ves | No 🗀 | | |
| Relinquished By: Date / Time Received By: Da | | | te / Time | Were samples received intact and properly preserved? Yes No | | | | | | | | | | | | | | |
| | | | | | ν, | | | , | Temp. | Blank | ζ | _°C | | | | | | |
| knig\newcoc | \xls | | | | | | | | | | | | <u> </u> | | | | • | |